

List of Tools and Extras
Carried by Each Tank.

- 1 chart book
- ✓ 1 Klaxon horn ✓
- ✓ 1 ten-liter can for extra oil
- ✓ 1 steel rope with hook on one end and eye on the other. 7/16" diameter, ten meters long
- ✓ 1 chain two and one-half meters long
- ✓ 1 five-ton jack
- ✓ 2 shovels
- ✓ 1 pick
- 2 Pyrene extinguishers
- 1 leather tool bag
- 1 hammer
- 1 bronze heading bar
- 1 large screw-driver
- 1 small screw-driver
- 1 small vise
- 2 adjustable end wrenches
- 4 double end flat wrenches
- 4 double end socket wrenches
- 1 large special wrench (for adjusting pulley wheel)
- 1 carburetor spray nozzle key
- 1 cotter pin puller
- 1 cold chisel (large)
- 1 cold chisel (small)
- 1 oil gun
- 1 grease gun
- 2 funnel *large, small.*
- 1 canvas pail
- 1 pair Universal pliers
- 2 meters of asbestos string packing
- 1 roll tire tape
- 2 leather straps
- 1 roll soft iron wire
- 1 chamois
- 1 measure stick for gas tank
- 1 pair bolt cutters
- 1 can cup grease
- 1 small motor cleaning brush
- 50 centimeters rubber tubing
- 5 liters of petrol
- 1 valve spring lifter
- 4 spark plugs
- 1 intake
- 1 exhaust valve
- 1 valve spring
- 2 meters of insulated wire
- 2 rubber tubes with special fastenings

- 2 pet cocks
- 4 links for fan belt
extra magneto parts
split washers
- 6 nuts and bolts. 5 millimeters
- 6 nuts and bolts. 10 millimeters
- 6 nuts and bolts. 12 millimeters
- 6 nuts and bolts. 14 millimeters
- 10 cotter pins. 1-1/2 millimeters
- 10 cotter pins. 2 millimeters
- 10 cotter pins. 3 millimeters
- 10 cotter pins. 6 millimeters
- 1 sponge
- 1 cleaning brush
- 1 triangle file
- 1 round file *square file*
(1 gas)
- 3 oiling cans (1 oil
(1 kerosene)
- 1 big oiling can
- solderless pipe connections
extra tubing
- 1 trouble lamp

5000 rd white

*glass light with cables
Battery & Bulbs.
pad locks + keys.*

*2 ethyl change bulbs & pipes
1 set minus copper
~~2 sets of...~~
1 pet jammed
1 gas jammed
1 water jammed
1 " can.*

Carrollford with

List of Tools and Extras
Carried by Battalion Repair Unit.

- 1 large machine shop truck with trailer carrying
dynamo and motor with sufficient power to
operate at least two lathes and drill presses.
electric drills, etc., including shop lighting
- 1 160 millimeter lathe (with complete set of tools) } mounted
- 1 drill press (very sensitive up to 16 millimeters) } inside
- 1 emery wheel } truck
- 3 vises
- 1 set metal drills (2 millimeters to 22 millimeters,
with 1/2 millimeter difference between each size)
- 4 braces with large assortment of bits
- 1 special ratchet brace
- 1 complete set of monkey wrenches (up to 500
millimeters length)
- 2 electric drills (1 slow speed for small holes and
one three-speed for large holes)
- 1 complete set of metal bits (2 to 22 millimeters)
- 1 complete set of metal augurs (2 to 22 millimeters)
- 1 complete set taps and dies (2 to 24 millimeters)
- 1 set of handles for holes for different size handles
- 1 blow torch for copper with soldering irons
- 1 blow torch for tin with soldering irons
- 2 pipe wrenches
- 1 complete set of socket wrenches
- 1 complete set of end wrenches

- 15 different kinds of pliers (cutting, flat, round, universal, etc.)
- 3 bolt cutters
- 2 bubble levels
- 2 plates for flattening out shims, etc.
- 1 marker
- 12 steel prick punches
- 10 cotter pin pullers
- set gauges
- 1 set of calipers inside (10 each)
- 1 set of calipers outside (10 each)
- 1 set of hammers (heavy to smallest)
- 1 bronze hammer
- 1 copper hammer
- 1 wood hammer
- 1 leather hammer
- 5 hack saws
- 12 dozen blades
- 2 adjustable ratchet drills
- 1 set of files (all kinds and sizes)
- 5 pieces of round bronze stock
- 4 breast drills and set of wood bits
- complete assortment of nuts, bolts, cotter pins, etc.

1 five-ton truck with trailer (equipment to set up shop at destination)

- 1 225 millimeter lathe
- bench and set of tools for lathe
- drill press (automatic)
- 1 three-ton demountable crane with chain tackle & winch

Blacksmith outfit

- hard forge
- anvil stand
- slack tube
- swedges
- sledge hammers
- punches
- tongs
- charcoal
- etc.

600 ft. Manila rope 1" & multiple lengths blocks.

- 1 workbench
- 1 acetyline welding outfit
- 1 cutter torch
- 3 tanks acetyline gas
- 3 three-ton jacks
- 5 five-ton jacks
- 10 steel ropes
- 6 crowbars, large *3ft 6"*
- 3 crowbars, small *6ft 3ft 6"*
- 2 pulleys and chains, with block and tackle
- 10 shovels
- 10 picks *3 hand assorted*
- 10 axes
- 5 hatchets
- 1 one piece cut 3 ft saw 2 - hammer

10 claw hammers 3 Maul planes

- 5 sledge hammers
- 25 12 Pyrene extinguishers
- 4 tarpaulins *large*
- 10 motor cleaning brushes
- 10 large cleaning brushes
- 5 oiling cans
- 12 canvas pails
- 100 empty sandbags *100 canvas net*
20x26
- chains
- stock of rubber tubing and connections
- stock of copper pipe
- stock of steel plate
- stock tool steel
- screw stock
- shafting

extra mufflers?

6 Brown shells

500# Colton waste

1 five-ton truck and trailer (to carry spare parts and stocks)

- longeron (1 complete, 1 dismantled)
- chariot (1 complete, 1 dismantled)
- chains, rollers, springs, etc.
- motor, gear box, clutches, D.M.
- magneto, carburetor, pulsator
- extra gas tanks, small and large

*two tanks
muffler rollers*

Guns

- 2 six-pounders
- 2 three-inch
- 3 machine guns

*special machine
+ small stocks.*